# Village of Pleasant Hill Ohio 2017 Drinking Water Consumer Confidence Report

The Pleasant Hill Board of Public Affairs is pleased to bring you our water quality report for 2017. This report is designed to inform you about the quality of water delivered to your tap everyday. We want you to know about the steps we take to ensure the quality of your water and our water resources. Our goal is to provide you with a safe and dependable supply of drinking water everyday.

Our water comes from three production wells located to the west of the village on Lauver Rd. The water is pumped from these three wells by 30 horsepower submersible pumps at a rate of 290 gallons per minute. It is then chlorinated before being pumped throughout the distribution system. The village uses approximately 75,000 gallons per day.

The Board of Public Affairs is committed to improving our water distribution system. For future projects the Village is looking into replacing the water mains and fire hydrants on South Maple St. and South Long St. and is in the construction phase of replacing Henry St., Pearson St., West North St. and Court Ave. Also looking at updating to new well pump controls at the well house and adding level controls at the water tower for more control and reliability.

Stan Fessler President BPA Kory Krofft BPA Member Von Fessler BPA Member The Ohio EPA recently completed a study of our water supply, to identify potential contaminant sources and provide guidance on protecting our drinking water source. According to the study, the aquifer that supplies water to Pleasant Hill has a high susceptibility to contamination. The determination was based on the following:

- \*The presence of a relatively thin layer of clay covering the aquifer.
- \*The presence of potential contaminant sources in our protection area.
- \*The presence of manmade contaminants in treated water. Samples collected since 1992 have contained nitrate levels above the level of concern. The levels have ranged from Below Detectable Limits to 7.0.

# What are sources of contamination to drinking water?

The sources of drinking water both tap water and bottled water includes rivers, lakes, streams, ponds. reservoirs, springs, and wells. As water travels over the surface of the land or through the ground, it dissolves naturally-occurring minerals and, in some cases, radioactive material, and can pick up substances resulting from the presence of animals or from human activity. Contaminants that may be present in source water include: (A) Microbial contaminants, such as viruses and bacteria, which may come from sewage treatment plants, septic systems, agricultural livestock operations and wildlife; (B) Inorganic contaminants, such as salts and metals, which can be naturally occurring or result from urban storm water runoff, industrial or domestic wastewater discharges, oil and gas production, mining, or farming; (C) Pesticides and herbicides, which may come from a variety of sources such as agriculture, urban storm water runoff, and residential uses; (D) Organic chemical contaminants, including synthetic and volatile organic chemicals, which are by-products of industrial processes and petroleum production, and can also come from gas stations, urban Strom water runoff, and septic systems; (E) radioactive contaminants, which can be naturally-occurring or be the result of oil and gas production and mining activities. In order to ensure that tap water is safe to drink, USEPA prescribes regulations which limit the amount of certain contaminants in water provided by public water systems. FDA regulations establish limits for contaminants in bottled water which must provide the same protection for public health. Drinking water, including bottled water, may reasonably be expected to contain at least small amounts of some contaminants. The presence of contaminants does not necessarily indicate that water poses a health risk. More information about contaminants and potential health effects can be obtained by calling the Environmental Protection Agency's Safe Drinking Water Hotline (1-800-426-4791).

## Who needs to take special precautions?

Some people may be more vulnerable to contaminants in drinking water than the general population. Immuno-compromised persons such as persons with cancer undergoing chemotherapy, persons who have undergone organ transplants, people with HIV/AIDS or other immune system disorders, some elderly, and infants can be particularly at risk from infection. These people should seek advice about drinking water from their health care providers. EPA/CDC guidelines on appropriate means to lessen the risk of infection by Cryptosporidium and other microbial contaminants are available from the Safe Drinking Water Hotline (1-800-426-4791).

### **New Lead Educational Paragraph**

"If present, elevated levels of Lead can cause serious health problems, especially for pregnant women and young children. Lead in drinking water is primarily from materials and components associated with service lines and home plumbing. Pleasant Hill Water System is responsible for providing high quality drinking water, but cannot control the variety of materials used in plumbing components. When your water has been sitting for several hours, you can minimize the potential for lead exposure by flushing your tap for 30 seconds to 2 minutes before using water for drinking or cooking. If you are concerned about lead in your water, you may have your water tested. Information on lead in drinking water, testing methods, and steps you can take to minimize exposure is available from the Safe Drinking Water Hotline at <a href="http://www.epa.gov/safewater/lead">http://www.epa.gov/safewater/lead</a>."

Nitrate in drinking water at levels above 10 ppm is a health risk for infants less than six months of age. High nitrate levels in drinking water can cause blue baby syndrome. Nitrate levels may rise quickly for short periods of time because of rainfall or agricultural activity. If you are caring for an infant you should ask advice from your health care provider.

The Ohio EPA requires regular sampling to ensure drinking water safety. Some contaminants are required to be monitored less than once per ye since many of the levels found do not frequently change. Some of our data, though accurate, may be more than a year old.

Nitrates 10ppm 10ppm 1.36ppm 1.36ppm NO 2017 Runoff from fertilizer use. Leaching from septic tanks. Erosion of natural deposits.  Residual Disinfectants  Total Chlorine ppm MRDLG=4 MRDL=4 1.145ppm 0.46 – 1.81ppm NO 2017 Water additive used to control  Disinfection Byproducts  HAA5 60ppb NA 1.273ppb 0 - 1.273ppb NO 2017 Shyroduct of drinking water chlorination  TTHMS 80ppb NA 3.860ppb NO 2017 Shyroduct of drinking water chlorination  Lead and Copper  Contaminant (Units) Action Level (AL) Results levels were less than AL Shyroduct of drinking water chlorination  A.L. A.L. Shyroduct of drinking water contamination  Copper 1.3ppm NA 207ppm NO 2017 Erosion of household plumbing systems.  Zero of 10 samples were found to have lead levels in excess of the copper action level of 1.3 ppm.  Corrosion of household plumbing systems.				LEVEL	RANGE					Typical source of	
SAMPES   SAMPES	Contaminant	MCI	MCLG	FOLIND	OF		Violat	tion	Year	contamination	
Discharge from drilling waste.	Contaminant	WOL	WIOLO	TOOND			Violat		roai	Contamination	
Barium 2ppm 2ppm .134ppm NA NO 2015 Discharge from drilling waste.  ALPHA, Gross 15pCi/L 0pCi/L 9.05pCi/l NA NO 2015 Certain minerals that are radioactive and may emit a form of radiation known as alpha radiation.  Nitrates 10ppm 10ppm 1.36ppm NO 2017 Residual Disinfectants  Total Chlorine ppm MRDLG=4 MRDL=4 1.145ppm 0.46 - 1.81ppm NO 2017 Water additive used to control Disinfection Byproducts  THAA5 60ppb NA 1.273ppb 0-3.860ppb NO 2017 By-product of drinking water chlorination  Disinfection Byproducts  THMS 80ppb NA 3.860ppb 0-3.860ppb NO 2017 By-product of drinking water chlorination  Lead and Copper  Contaminant (Units) Level (AL) Results over the AL					SAMPES						
Barium 2ppm 2ppm .134ppm NA NO 2015 Discharge from metal refinery. Erosion of natural deposits.  ALPHA, Gross 15pCi/L 0pCi/L 9.05pCi/l NA NO 2015 Erosion of natural deposits of certain minerals that are radioactive and may emit a form of radiation known as alpha radiation.  Nitrates 10ppm 10ppm 1.36ppm 1.36ppm NO 2017 Runoff from fertilizer use. Leaching from septic tanks. Erosion of natural deposits.  Residual Disinfectants  Total Chlorine ppm MRDLG=4 MRDL=4 1.145ppm 1.81ppm NO 2017 Water additive used to control Disinfection Byproducts  HAA5 60ppb NA 1.273ppb 1.273ppb NO 2017 By-product of drinking water chlorination  TTHMs 80ppb NA 3.860ppb 0-3.860ppb NO 2017 By-product of drinking water chlorination  Lead and Copper  Contaminant (Units) Action Level (AL) Individual Results over the AL	Inorganic Contaminant	is	1							B: 1 ( 130)	
ALPHA, Gross 15pCi/L 0pCi/L 0pCi/L 9.05pCi/l NA NO 2015 certain minerals that are radioactive and may emit a form of radiation.  Nitrates 10ppm 10ppm 1.36ppm 1.36ppm NO 2017 Runoff from fertilizer use. Leaching from septic tanks. Erosion of natural deposits.  Residual Disinfectants  Total Chlorine ppm MRDLG=4 MRDL=4 1.145ppm 0.46 - 1.81ppm NO 2017 Water additive used to control 1.81ppm NO 2017 Disinfection Byproducts  HAA5 60ppb NA 1.273ppb 0.3.860ppb NO 2017 By-product of drinking water chlorination  TTHMs 80ppb NA 3.860ppb 0.3.860ppb NO 2017 By-product of drinking water chlorination  Lead and Copper  Contaminant (Units) Action Level (AL) Results levels were less than AL Copper NO 2017 Individual Results levels were less than AL Copper NO 2017 Corrosion of household plumbing systems.  A.L. A.L. Copper NO 2017 Corrosion of household plumbing systems.  Corrosion of household plumbing systems.	Barium	2ppm	2ppm	.134ppm	NA		NO		2015	Discharge from metal refinery.	
Nitrates 10ppm 10ppm 1.36ppm 1.36ppm NO 2017 Leaching from septic tanks. Erosion of natural deposits.  Residual Disinfectants  Total Chlorine ppm MRDLG=4 MRDL=4 1.145ppm 0.46 — 1.81ppm NO 2017 Water additive used to control  Disinfection Byproducts  HAA5 60ppb NA 1.273ppb 0.3.860ppb NO 2017 By-product of drinking water chlorination  TTHMs 80ppb NA 3.860ppb 0.3.860ppb NO 2017 By-product of drinking water chlorination  Lead and Copper  Contaminant (Units) Action Level (AL) Results over the AL Results ov	ALPHA, Gross	15pCi/L	0pCi/L	9.05pCi/l	NA		NO		2015	certain minerals that are radioactive and may emit a form of radiation known as alpha	
Total Chlorine ppm MRDLG=4 MRDL=4 1.145ppm 0.46 - 1.81ppm NO 2017 Water additive used to control  Disinfection Byproducts  HAA5 60ppb NA 1.273ppb 0 - 1.273ppb NO 2017 By-product of drinking water chlorination  TTHMs 80ppb NA 3.860ppb 0-3.860ppb NO 2017 By-product of drinking water chlorination  Lead and Copper  Contaminant (Units) Action Level (AL) Results over the AL Power the AL Standard Results over the AL Copper 1.3ppm NA 2.207ppm NO 2017 Erosion of household plumbing systems.  Zero of 10 samples were found to have lead levels in excess of the copper action level of 1.3 ppm.  Corrosion of household plumbing systems.	Nitrates	10ppm	10ppm	1.36ppm	1.36ppm	36ppm		2017		Leaching from septic tanks.	
Total Chlorine ppm MRDLG=4 MRDL=4 1.145ppm 1.81ppm NO 2017  Disinfection Byproducts  HAA5 60ppb NA 1.273ppb 0-3.860ppb NO 2017  TTHMs 80ppb NA 3.860ppb 0-3.860ppb NO 2017  By-product of drinking water chlorination  Typical source of contaminant (Units)  Level (AL) Results over the AL Violation Year contamination  A.L. A.L. A.L. Copper NO 2017 Erosion of household plumbing systems.  Zero of 10 samples were found to have lead levels in excess of the copper action level of 1.3 ppm.  A.L. A.L. Corrosion of household plumbing systems.	Residual Disinfectants										
HAA5  60ppb  NA  1.273ppb  0 - 1.273ppb  NO  2017  By-product of drinking water chlorination  TTHMs  Action Lead and Copper  Contaminant (Units)  Action Level (AL) Results over the AL  A.L.  A.L.  A.L.  207ppm NO  2017  Corrosion of household plumbing systems.  Erosion of natural deposits.  Zero of 10 samples were found to have lead levels in excess of the copper action level of 1.3 ppm.  Corrosion of household plumbing systems.  Corrosion of household plumbing systems.	Total Chlorine ppm	MRDLG=4	MRDL=4	1.145ppm			NO		2017	Water additive used to control	
HAA5  60ppb  NA  1.273ppb  1.273ppb  NO  2017  Chlorination  By-product of drinking water chlorination  Evel (AL)  Copper  A.L.  A.L.  1.3ppm  NA  207ppm  NO  2017  Chlorination  NO  2017  Chlorination	Disinfection Byproducts	1	1								
TTHMs 80ppb NA 3.860ppb 0-3.860ppb NO 2017 chlorination  Lead and Copper  Contaminant (Units)  Action Level (AL) Results over the AL  A.L. A.L. A.L. 207ppm NO 2017 Erosion of household plumbing systems.  Zero of 10 samples were found to have lead levels in excess of the copper action level of 1.3 ppm.  A.L. A.L. Corrosion of household plumbing systems.	HAA5	60ppb	NA	1.273ppb			NO		2017		
Contaminant (Units)  Action Level (AL)  Results over the AL  A.L.  Copper  A.L.  A.L.  A.L.  A.L.  Zero of 10 samples were found to have lead levels in excess of the copper action level of 1.3 ppm.  Action Level (AL)  Results over the AL  Violation Year  Contamination  Corrosion of household plumbing systems.  Erosion of natural deposits.  Corrosion of household plumbing systems.  Corrosion of household plumbing systems.	-	80ppb	NA	3.860ppb	0-3.860ppl	b	NO		2017		
Contaminant (Units)  Action Level (AL) Results over the AL  A.L. Copper  A.L. A.L.  Individual Results over the AL  A.L.  A.L.  A.L.  Zero of 10 samples were found to have lead levels in excess of the copper action level of 1.3 ppm.  A.L.  A.L.  Corrosion of household plumbing systems.  Erosion of natural deposits.  Corrosion of household plumbing systems.  Corrosion of household plumbing systems.  Corrosion of household plumbing systems.											
Copper 1.3ppm NA .207ppm NO 2017 Erosion of natural deposits.  Zero of 10 samples were found to have lead levels in excess of the copper action level of 1.3 ppm.  A.L. A.L. Corrosion of household plumbing systems.			Results over the	90% of test levels were	Violation	Ye	ear				
Copper 1.3ppm NA .207ppm NO 2017 Erosion of natural deposits.  Zero of 10 samples were found to have lead levels in excess of the copper action level of 1.3 ppm.  A.L. A.L. Corrosion of household plumbing systems.		A.L.	A.L.								
A.L. Corrosion of household plumbing systems.	Copper						7 Erosion of natural deposits.				
plumbing systems.				e round to hav	e iead ievels T	s in	exces				
		\ \.L.	A.L.						plumbing systems.		
1 out of 10 samples were found to have lead levels in excess of the lead action level of 15 ppb.	Lead	15ppb	252ppb samples wer	5.12ppb	NO ve lead level:		017 exces	Erosion of natural deposits.			

- \*Maximum Contaminant Level Goal (MCLG): The level of a contaminant in drinking water below which there is no known or expected risk to health. MCLGs allow for a margin of safety.
- \*Maximum Contaminant level (MCL): The highest level of contaminant that is allowed in drinking water. MCLs are set as close to the MCLGs as feasible using the best available treatment technology.
- \*Parts per Million (ppm) or Milligrams per Liter (mg/L) are units of measure for concentration of a contaminant. A part per million corresponds to one second in a little over 11.5 days.
- \*Parts per Billion (ppb) or Micrograms per Liter (ug/L) are units of measure for concentration of a contaminant. A part per billion corresponds to one second in 31.7 years.
- \*picocuries per Liter (pCi/L)

# License to Operate (LTO) Status.

"We have a current, unconditioned license to operate our water system."

### WHAT CAN YOU DO?

By implementing appropriate protective measures, we can minimize the risk of future contamination. You can obtain more information about the EPA's Source Water Assessment by calling 676-3241 and requesting a copy. Any Questions about the CCR, or would like to receive a paper copy call Jeff Derksen at 676-3241. We welcome your participation in the decisions regarding your water service by attending a Board of Public Affairs Meeting. These meetings are held the third Monday of the month at 7:30 p.m. in the Village Meeting Hall @ 200 Walnut St.